



The plant is situated in Czech Republic. Due to the contaminants in raw water, a sophisticated pre-treatment was implemented in order to feed the R.O. membranes with water of suitable quality.

Location: Czech Republic

Industry: Tyre Manufacturing

Raw Water: Low salinity water 625 m³/day

Product Water: TDS < 20 mg/l

